



---


# Optical acceptance of the DDK connectors or What exactly do you mean by transmission?

Howard Budd




# Light Injector

- ◆ Source part of the light injector is constructed
- ◆ A wand source is inserted into the hole in the green piece
- ◆ The purple and cyan piece is scintillator
- ◆ The scintillator excites WLS fiber
- ◆ For testing cables LED and pin diodes will be installed






# Transmission using Light Injector



- ◆ Insert 40 cm jumper into left bottom connector
- ◆ Insert 205 cm cable to be tested onto jumper
- ◆ Plug 90cm pigtail with Single Fiber Ferrules into Cable to be tested
- ◆ Single Fiber Ferrules go directly on light mixer of R580-17
- ◆ Measure all the fibers with the Single Fiber Ferrules
- ◆ Cut cable in half and insert connectors on both ends




# Transmission Using Light Injector



- ◆ Eileen in Lab 7 polishes the connectors
- ◆ 2 halves connected together in the identical way as before
- ◆  $\text{transmission (after cut)/(before cut)}$
- ◆ Since it's a ratio the amount of light injected into the light by the light injector should not matter.
- ◆ Light Injector Fiber Number 1 is at the top of the connector in the Light Injector Box.
- ◆ Transmission is plotted for each Light Injector Fiber Number




# Setup in the Dark Box, with Cut Cable





# Transmission of DDK connectors



- ◆ This has been shown at 2 Friday meetings
  - ◆ 14 % difference between fiber 1 & 8
- ◆ This pattern doesn't make sense
  - ◆ When mated the connectors get mirror imaged
  - ◆ All ferrules are made by the same mold
  - ◆ DDK Hole 1- DDK Hole 8, 2-7 ...
- ◆ These connectors are polished by the diamond moving along the long end
  - ◆ This effect is not due to the fiber polishing
  - ◆ The test is not shown





## So What is Wrong with the Connector?

---

- ◆ We rotated the box by 180 degrees and got the same answer
- ◆ Eva's measurements at Sci Det indicate the connector is fine
- ◆ I tried to mechanically demonstrate their failure
  - ◆ I plugged 2 ferrules in a DDK box
  - ◆ I took 2 of the 48 mil (1.22mm) gauge pins and inserted them in holes 1 and 8, through both connectors
  - ◆ They went through fairly easily
  - ◆ A 49 mil (1.244mm) mil gauge pin does not go through any hole in any connector
  - ◆ This means the holes 1 and hole 8 match to better than 1 mil
  - ◆ This agrees with Eva's measurement
  - ◆ This test implies that the holes are meeting straight on since the pins are straight
- ◆ The DDK connectors and their box are fine



# Cut & Uncut Cable Top and Bottom




- ◆ Take 2 cables
  - ◆ 2 m clear cable (control cable)
  - ◆ two 1m clear cables connected together
    - » (used for the previous transmission test)
- ◆ Measure both on the bottom left connector on the light injector
- ◆ Measure both on the top left on the light injector






# Cut & Uncut Cables Top and Bottom



- ◆  $\frac{((\text{bottom 2 1m cables})/(\text{Bot 2 m cable}))}{((\text{top 2 1m cables})/(\text{top 2 m cable}))}$
- ◆  $(2 \text{ 1m cable})/(2\text{m cable})$  is like a transmission = (cut/uncut)
- ◆ Transmission measured in the bottom connector is not the same transmission measured in the top connector
- ◆ Transmission is a function of the light injector fiber number
- ◆ Looks like it's the problem is measurement not the connectors





# Can We Explain This Effect?



- ◆ If the light angular distributions, the modes, are different then the different reflections at the connector interface may be causing the effect.
- ◆ We can test this by putting grease in the connector
- ◆ The grease removes the differences in index of refraction across the gap
- ◆ The increase in transmission, about 16%, is independent of the fiber number
- ◆ Note that the transmission for injector fiber 1 for this cable is 86%, so roughly all the light is being transmitted with grease
  - ◆ However, there is some error in this because the clear pigtail had to be replaced between the transmission test and this test




# This Light Difference is Hard to Kill



- ◆ We would expect that the difference would be removed as the light crosses a connector
- ◆ Remember the difference is big 14%
- ◆ The previous measurements have 3 DDK connections beside the one being tested
- ◆ Lets add another clear jumper
  - ◆ Out of light injector there are is a 40 cm jumpers and 37 cm jumper





# The additional clear jumper has no effect on removing the difference



- ◆ Come hell or high water, once the light is created with this difference it will keep it, or it will be recreated it, knowing which injector fiber it came from
- ◆ I call this effect the TMC
  - ◆ Transmission Measurement Conundrum
  - ◆ Not: Target Mass Correction
- ◆ Cladding light differences should have been removed by all these jumpers
  - ◆ Cladding light is defined by light that propagates by reflecting in outer cladding air interface
  - ◆ 1.8 m of clear before it hits this junction, with 1.9 m of addition fiber to the PMT




# Displacing the source



- ◆ Bob Flight suggested displacing the source
- ◆ Bottom left connector-> 40 cm jumper->1 or 2 cables->90 cm pigtail->PMT
- ◆  $\frac{((\text{cut/uncut}) \text{ source up } 4.2 \text{ cm})}{(\text{cut/uncut}) \text{ source in normal place}}$
- ◆ Ratio of transmission measured with the bottom connector with source in 2 different positions
- ◆ Ave = 1.03, Clearly demonstrates the TMC is not due to difference between pigtails in the light injector




# Before Measurement, Coex Scintillator



- ◆ The TMC tells us a transmission measurement should simulate the real apparatus
- ◆ 1/2 m coextruded scintillator illuminated by source
- ◆ 1m WLS pigtail
  - ◆ Made 2 pigtails
- ◆ 205 cm clear cable
- ◆ 90 cm clear pigtail with single fiber ferrule
- ◆ R580-17 Green Extended Tube
- ◆ Measure all fiber with Single Fiber Ferrules




# Cut Measurement



- ◆ Insert connector in 205 m cable
- ◆ Eileen polishes the connectors
- ◆ Measured the same way as before



# Transmission Using Coextruded Scin




- ◆ Ave = 82% and fairly independent of hole number.
- ◆ The result for the 2 pigtails seem to be different
  - ◆ Not sure why they should be different but maybe not enough measurements to tell





# Transmission, Light Injector Top Connector



- ◆ Reasonable flat
  - ◆ Fiber 1 low is probably from the TMC
  - ◆ Remember this is the top connector on the injector box
- ◆ Transmission is 80.5%
- ◆ Note from the TMC its not clear what this transmission means
  - ◆ If we had made the initial measurement using the top connector we would not have seen the light depend on fiber number
  - ◆ We would have ignored fiber 1 being low
  - ◆ We would be ignorant to the TMC and thought this transmission was a defined number
  - ◆ “And there are things we don’t know that we don’t know”



# Conclusion

---

- ◆ Optically the connectors pass – ferrule is fine
  - ◆ The hole position and diameter look very good
  - ◆ The holes in the ferrule align to better than a mil, better than we had hoped
- ◆ We were confused by the TMC, but now “there are things that we know that we don’t know.”




# Backup Slides

---

- ◆ Measurements not shown




# Polishing direction holes 1-8 & 8-1



- ◆ The Connectors near the light injector box are polished with the same orientation
- ◆ The connectors shown in the red points are polished with the same orientation,
  - ◆ This means 1st hole polished matches with the 8 th hole polished...
- ◆ The connectors shown in blue points are polished with the opposite orientation to their mate
  - ◆ 1<sup>st</sup> fibers polished mate together ...
- ◆ Polishing is not the problem
- ◆ (Fiber 4 is bad in the clear pigtail)



# So What Is Wrong with the Connector?



- ◆ For this plot we measure a cut cable
  - ◆ One previously used in a transmission test
- ◆ The DDK box is rotated by 180 degrees and cable remeasured
  - ◆ This is not exactly the rotation one wants to do to test the box, but this is the only one can due because of the key
- ◆ The DDK Box appears to be fine
- ◆ In addition the RMS of reconnection is 0.6%, it is tight.
- ◆ Bob Flight will be machining out a key so we can do exactly the correct test